


Samuel Smith Incorporated  
424 West Main Street  
Evans City, PA 16063  
Dear Sirs:

I am writing in regards to the performance of the Halex Coil Magnetic Filtration System.

I have been using the Coil for about 9 months on our 720 Hydro Ax, which uses Sunstran Hydraulic pumps and motors. I placed the coil on one of the two hydraulic filters. After 500 hours of operation I removed both filters. To my delight the filter with the coil had collected far more particles than the filter without the coil.

Since the tractor has a common reservoir system, the only difference could have been the coil. I was also delighted to see not only steel but brass and other non-ferrous particles in the filter. Which is more than I expected from this device.

Sincerely and Thanks,



Kenneth Nagle  
Head Mechanic  
Samuel Smith Inc.